

State of California—Health and Welfare Agency  
Form Approved OMB No. 2050-0039 (Expires 9-30-88)  
Please print or type. (Form designed for use on elite (12-pitch typewriter).

Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

LASSO

Maintenance Area 05

Maintenance Area 05

611 Jackson Street

Los Angeles, Ca. 90012

625-6868

Safety Section Rm. 215

1425 S. San Pedro St.

Los Angeles, Ca. 90015

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. C A D 9 8 1 4 2 3 8 1 7		Manifest Document No. 0 5 1 1 2 5		2. Page 1 of		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Maintenance Area 05 611 Jackson Street Los Angeles, Ca. 90012		4. Generator's Phone 625-6868		5. State Manifest Document Number 87630831		6. State Generator's ID H S H 0 3 6 0 1 7 5 0 5		7. State Transporter's ID 80485 904878	
5. Transporter 1 Company Name Omega Recovery Services		6. US EPA ID Number C A D 0 4 2 2 4 5 0 0 1		8. State Transporter's ID 213-698-0991		9. State Facility's ID C A D 0 4 2 2 4 5 0 0 1		10. Facility's Phone 213-698-0991	
7. Transporter 2 Company Name Omega Recovery Services		8. US EPA ID Number		9. State Transporter's ID		10. State Facility's ID		11. Facility's Phone	
9. Designated Facility Name and Site Address Omega Recovery Services 12512 Whittier Blvd. Whittier, California 90602		10. US EPA ID Number C A D 0 4 2 2 4 5 0 0 1		11. State Facility's ID		12. Facility's Phone			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.	
a. Flammable, Liquid N.A. 1263 (D001)		1 3 D M		1 1 6 2				State EPA/Other	
b.								State EPA/Other	
c.								State EPA/Other	
d.								State EPA/Other	
J. Additional Descriptions for Materials Listed Above Al Mineral Spirits 90% A2 Oil		K. Handling Codes for Wastes Listed Above a. 01 b. c. d.							
15. Special Handling Instructions and Additional Information Keep Container Upright And Sealed. Avoid Spillage. Secure Container To Vehicle To Avoid Spillage And Movement During Transit.									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name MIKE MILETTI		Signature Mike Milette		Month Day Year 1 7 1 1 8 8					
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name JAVIER HERNANDEZ		Signature Javier Hernandez		Month Day Year 1 0 7 1 1 8 8			
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature		Month Day Year			
19. Discrepancy Indication Space									
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.									
Printed/Typed Name FRANK FORD		Signature Frank Ford		Month Day Year 1 0 7 1 1 8 8					

DHS 8022 A (1/87)

EPA 8700-22

(Rev. 9-86) Previous editions are obsolete.

White: TSD/ SENDS THIS COPY TO DOHS WITHIN 30 DAYS

To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550